

**GUJARAT TECHNOLOGICAL UNIVERSITY****Diploma Engineering - SEMESTER-IV • EXAMINATION – SUMMER 2013****Subject Code: 342901****Date: 05-06-2013****Subject Name: Yarn Manufacturing Technology - II****Time: 10:30 am - 01:00 pm****Total Marks: 70****Instructions:**

1. Attempt all questions.
2. Make suitable assumptions wherever necessary.
3. Figures to the right indicate full marks.
4. English version is considered to be Authentic.

- Q.1** (a) Explain the Modern development in Speed frame machine. **07**  
 (b) Explain the passage of material in Ring frame with neat sketch. **07**
- Q.2** (a) Draw a sketch showing passage of material in Comber machine. **07**  
 (b) Explain the principle of Twisting and Winding in Speed frame machine. **07**  
 OR  
 (b) Explain the principle of Twisting and Winding in Ring frame machine. **07**
- Q.3** (a) Explain any one drafting system used in speed frame machine. **07**  
 (b) Explain cycle of operation in comber with neat sketch. **07**  
 OR
- Q.3** (a) Name the different types of rings are used in Ring frame & explain Antiwedge ring in details. **07**  
 (b) Explain cop building mechanism in Ring frame machine. **07**
- Q.4** (a) Explain Wet doubling system. **07**  
 (b) Explain the production method of flake yarn. **07**  
 OR
- Q. 4** (a) Explain the production method of spot yarn. **07**  
 (b) Explain Roving waste opener with neat sketch. **07**
- Q.5** (a) Calculate production of Ring frame machine in Kgs & Lbs from the following particulars. (1) Front roll RPM = 220 (2) Front roll diameter = 27 mm (3) Count of yarn = 40s Ne (4) Efficiency = 94% (5) T.P.I = 25 (6) Working time = 8 Hrs (7) No of spindle = 1200 **07**  
 (b) Explain the cause and remedies of any two yarn fault . **07**  
 OR
- Q.5** (a) Explain the cause and remedies of any two Package fault . **07**  
 (b) Calculate production of Speed frame machine in Kgs from the following particulars. (1) Spindle speed = 850 RPM (2) Hank of Roving = 0.9 (Ne) (3) No of spindle = 120 (4) Efficiency = 85% (5) Twist Multiplier = 1.16 (6) Working time = 8 Hrs **07**

\*\*\*\*\*

ગુજરાતી

- પ્રશ્ન. ૧ અ સ્પીડફેમમાં મોડન ડેવલપમેન્ટ સમજાવો. ૦૭  
 બ રિંગફેમમાં મટિરિયલ નો માર્ગ આકૃતી સાથે સમજાવો. ૦૭
- પ્રશ્ન. ૨ અ કોબર મશીન માં મટિરિયલ નો માર્ગ દર્શાવતી આકૃતી દોરો. ૦૭  
 બ સ્પીડફેમમાં ટવીસ્ટિંગ અને વાઇલ્ડિંગ નો સિદ્ધાંત સમજાવો. ૦૭
- અથવા
- બ રિંગફેમમાં ટવીસ્ટિંગ અને વાઇલ્ડિંગ નો સિદ્ધાંત સમજાવો. ૦૭
- પ્રશ્ન. ૩ અ સ્પીડફેમમાં ગમેતે એક ડ્રાફ્ટિંગ સિસ્ટમ સમજાવો. ૦૭  
 બ કોમ્બરમાં સાઇકલ ઓફ ઓપરેશન આકૃતિ સાથે સમજાવો. ૦૭
- અથવા
- પ્રશ્ન. ૩ અ રિંગફેમ માં વપરાતી જુદા જુદા પ્રકારની રિંગના નામ લખો અને એટીવેજ રિંગ વિગતે સમજાવો. ૦૭  
 બ રિંગફેમ માં કોપ બિલ્ડિંગ મેકેનિઝમ સમજાવો. ૦૭
- પ્રશ્ન. ૪ અ વેટ ડબલિંગ સિસ્ટમ સમજાવો. ૦૭  
 બ ફ્લેક યાર્ન નું ઉત્તપાદન સમજાવો. ૦૭
- અથવા
- પ્રશ્ન. ૪ અ સ્પોટ યાર્ન નું ઉત્તપાદન સમજાવો. ૦૭  
 બ રોવિંગ વેસ્ટ ઓપનર આકૃતિ સાથે સમજાવો. ૦૭
- પ્રશ્ન. ૫ અ નીચેની વિગતો પરથી રિંગફેમનું ઉત્તપાદન Kgs અને Lbs માં શોધો. ૦૭  
 (૧) ફ્રન્ટ રોલર આરપીએમ = ૨૨૦ (૨) ફ્રન્ટ રોલર ડાયામીટર = ૨૭ એમએમ  
 (૩) યાર્ન કાઉન્ટ = ૪૦ (Ne) (૪) કાર્યક્ષમતા = ૯૪% (૫) ટી પી આઇ = ૨૫  
 (૬) કામનો સમય = ૮ કલાક (૭) સ્પીડલ ની સંખ્યા = ૧૨૦૦  
 બ ગમે તે બે યાર્ન ફોલ્ટ ના કારણો તથા ઉપાયો સમજાવો. ૦૭
- અથવા
- પ્રશ્ન. ૫ અ ગમે તે બે પેકેજ ફોલ્ટ ના કારણો તથા ઉપાયો સમજાવો. ૦૭  
 બ નીચેની વિગતો પરથી સ્પીડફેમનું ઉત્તપાદન Kgs અને Lbs માં શોધો. ૦૭  
 (૧) સ્પીડલ આરપીએમ = ૮૫૦ (૨) રોવિંગ નો હેક = ૦.૯  
 (૩) સ્પીડલ ની સંખ્યા = ૧૨૦ (૪) કાર્યક્ષમતા = ૮૫%  
 (૫) ટ્રિવિસ્ટ મલ્ટીપ્લાયર = ૧.૧૬ (૬) કામનો સમય = ૮ કલાક

\*\*\*\*\*