



GUJARAT TECHNOLOGICAL UNIVERSITY**Diploma Engineering - SEMESTER-V • EXAMINATION – SUMMER • 2015****Subject Code: 352404****Date: 12-05-2015****Subject Name: Control System****Time: 02:30 pm - 05:00 pm****Total Marks: 70****Instructions:**

1. Attempt all questions.
2. Make suitable assumptions wherever necessary.
3. Figures to the right indicate full marks.
4. English version is considered to be Authentic.

- Q.1** (a) Describe closed loop control system with block diagram and one example. **07**
 (b) Compare open loop and Closed loop control system. **07**
- Q.2** (a) Define transfer function. Derive transfer function of given electrical network **07**



- (b) Explain anti-aircraft radar tracking control system. **07**
 OR
 (b) Explain Temperature control as feedback control system. **07**
- Q.3** (a) Explain first order unity feedback closed loop control system subjected to unit step response. **07**
 (b) A second order unity feedback control system has a open loop transfer function given by $G(s) = \frac{25}{s^2 + 8s + 25}$. If the system initially at rest is subjected to a unit impulse input at $t=0$, find out natural frequency of oscillation (ω_n) and Damping ratio (ξ), rise time and pick time. **07**
 OR
Q.3 (a) Explain first order closed loop unity feedback control system subjected to unit impulse response. **07**
 (b) Consider the system shown in fig. Determine the value of “A” such that damping ratio is 0.8 also obtain the value of rise time and max overshoot. **07**



- Q.4** (a) Describe potentiometer as a error detector with block diagram using Laplace transform. **07**
 (b) Describe working of integral control system with block diagram. **07**
 OR
Q.4 (a) Describe synchro as a error detector. **07**
 (b) Describe working of derivative control system with block diagram. **07**


- Q.5** (a) Find the transfer function with block diagram of field controlled D.C. motor. **07**
- (b) The characteristic equation for feedback control system is $s^3 + 2ks^2 + (k + 2)s + 4 = 0$. Determine the value of k for the system to be marginally stable. **07**

OR

- Q.5** (a) Find the transfer function with block diagram of armature controlled D.C. motor. **07**
- (b) The open loop transfer function of unity feedback system is given by $\frac{k}{s(1+2s)(1+6s)}$. Find the range of value of "K" so that system is absolutely stable. **07**

ગુજરાતી


- પ્રશ્ન. ૧ અ કોઈપણ એક ઉદાહરણ અને બ્લોક ડાયાગ્રામ સાથે ક્લોઝ લૂપ કન્ટ્રોલ સીસ્ટમ વર્ણવો. ૦૭
- બ ઓપન લૂપ અને ક્લોઝ લૂપ કન્ટ્રોલ સીસ્ટમ ને સરખાવો. ૦૭
- પ્રશ્ન. ૨ અ ટ્રાન્સફર ફંક્શન ને વ્યાખ્યાયિત કરો. નીચેની ઇલેક્ટ્રિકલ સર્કિટ ટ્રાન્સફર ફંક્શન તારવો. ૦૭



- બ એન્ટિ એર ક્રાફ્ટ રડાર ટ્રેકિંગ કન્ટ્રોલ સીસ્ટમ સમજાવો. ૦૭
- અથવા
- બ ટેમ્પરેચર કન્ટ્રોલ ને ફીડબેક કન્ટ્રોલ સીસ્ટમ વડે સમજાવો. ૦૭
- પ્રશ્ન. ૩ અ યુનિટ સ્ટેપ ઇનપુટ આપેલી યુનિટી ફીડબેક ફર્સ્ટ ઓર્ડર ક્લોઝ લૂપ કન્ટ્રોલ સીસ્ટમ સમજાવો. ૦૭
- બ સેકન્ડ ઓર્ડર યુનિટી ફીડબેક કન્ટ્રોલ નુ ઓપન લૂપ ટ્રાન્સફર ફંક્શન $G(s) = \frac{25}{s^2 + 8s + 25}$ છે. જો સીસ્ટમ શરૂઆત માં રેસ્ટ હોય અને ઇનપુટ તરીકે યુનિટ ઇમ્પલ્સ આપેલ હોય તો નેચરલ ફ્રીક્વન્સી ઓફ ઓસ્સીલેશન, ડેમ્પીંગ રેસીયો, રાઈસ ટાઈમ અને પીક ટાઈમ શોધો. ૦૭

અથવા

- પ્રશ્ન. ૩ અ યુનિટ ઇમ્પલ્સ ઇનપુટ આપેલી યુનિટી ફીડબેક ફર્સ્ટ ઓર્ડર ક્લોઝ લૂપ કન્ટ્રોલ સીસ્ટમ સમજાવો. ૦૭
- બ નીચે આપેલી કન્ટ્રોલ સીસ્ટમ માટે “A”, રાઈઝ ટાઈમ અને મેક્સીમમ ઓવર શૂટ ની કીમત શોધો જ્યાં ડેમ્પીંગ રેસીયો 0.8 છે. ૦૭



- પ્રશ્ન. ૪ અ લાપ્લાસ ટ્રાન્સફોર્મ નો ઉપયોગ કરી પોટેન્સિયોમીટર મીટર નો એરર ડિટેક્ટર તરીકે નો બ્લોક ડાયાગ્રામ શોધો. ૦૭
- બ બ્લોક ડાયાગ્રામ સાથે ઇન્ટીગ્રલ કન્ટ્રોલ સીસ્ટમ નુ કાર્ય સમજાવો. ૦૭

અથવા

- પ્રશ્ન. ૪ અ સિંક્રો ને એરર ડિટેક્ટર તરીકે સમજાવો. ૦૭
બ બ્લોક ડાયાગ્રામ સાથે ડેરીવેટીવ કન્ટ્રોલ સીસ્ટમ નુ કાર્ય સમજાવો. ૦૭
- પ્રશ્ન. ૫ અ ફીલ્ડ કન્ટ્રોલ ડી.સી. મોટર નુ ટ્રાંસ્ફર ફંક્શન બ્લોક ડાયાગ્રામ સાથે શોધો. ૦૭
બ ફીલ્ડ કન્ટ્રોલ સીસ્ટમ માટે નુ કેરેક્ટેરીસ્ટીક સમીકરણ $s^3 + 2ks^2 + (k + 2)s^1 + 4 = 0$ છે. માર્જીનલી સીસ્ટમ માટે “K” ની કીમત શોધો. ૦૭

અથવા

- પ્રશ્ન. ૫ અ આર્મેચર કન્ટ્રોલ ડી.સી. મોટર નુ ટ્રાંસ્ફર ફંક્શન બ્લોક ડાયાગ્રામ સાથે શોધો. ૦૭
બ યુનીટી ફીલ્ડ કન્ટ્રોલ સીસ્ટમ માટે નુ ઓપન લૂપ ટ્રાંસ્ફર ફંક્શન $\frac{k}{s(1+2s)(1+6s)}$. ૦૭
છે. એબ્સોલ્યુટલી સ્ટેબલ સીસ્ટમ માટે “K” ની શ્રેણી શોધો.
